LA-UR- 04-3449.

Approved for public release; distribution is unlimited.

### Abstract # LA-UR-04-1620

Title:

The Los Alamos National Laboratory 94/100-1 Materials Stabilization and Deinventory Project

Author(s):

Leo P. Archuleta, NMT-4 Nancy M. Gallegos, NMT-4 Leo D. Urbina, NMT-4

Submitted to:

American Glovebox Conference San Diego, California July 19-21, 2004



Form 836 (8/00)



Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by the University of California for the U.S. Department of Energy under contract W-7405-ENG-36. By acceptance of this article, the publisher recognizes that the U.S. Government retains a nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication



# THE LOS ALAMOS NATIONAL LABORTORY 94/00-1 MATERIALS STABILIZATION AND DEINVENTORY PROJECT

Nancy M. Gallegos, Leo D. Urbina, Leo P. Archuleta, Elizabeth A. Ronquillo, Priscilla L Davis, Simon Balkey, Wayne A. Punjak, Robert A. Vigil, Tony Drypolcher

Special nuclear material (SNM) in the Los Alamos National Laboratory (LANL) inventory that has been declared excess to programmatic needs is comprised of a large variety of chemical and physical forms. Many of these nuclear material items have been identified by the Defense Nuclear Facilities Safety Board (DNFSB) as a potential high risk to LANL workers and have been targeted for stabilization in recommendations DNFSB 94-1 and 00-1. In addition, vault space at the LANL Plutonium Facility is at a premium due to various ongoing programmatic missions and a lack of available disposition pathways. For these reasons LANL requested, and was granted by Department of Energy (DOE), a variance to terminate safeguards on attractiveness level D SNM items meeting the variance criteria. Materials meeting these criteria have been brought from the vault to the operating floor and opened in a hood or the glovebox line. Each item is inspected by a subject matter expert to: 1) verify there is no programmatic need for the item, and 2) determine if the item should be discarded as waste or sent for recovery. Items selected for discard are inspected by waste management personnel to ensure they meet the Waste Isolation Pilot Plant (WIPP) criteria for acceptance. This includes verification of the acceptable knowledge as well as the absence of items prohibited for disposal at WIPP. The item(s) are sent to waste management for packaging and certification for final transfer to WIPP. This poster presents an overview of the LANL Plutonium Facility disposition effort and progress to date.



Vault Storage



**Items For Introduction** 



Items To Be Opened
Inside Hood



Bagging Out Verified Items



TA-55 Standard Packaging



Filtered Bags Required



**Disposal Item** 



**Inner Can** 



Old Bag out with Item



**Inner Containment** 



**Opening Item For Introduction** 



Bag out with Item



Item Removal



Verifying Integrity Of Bag out Bag



Visual Inspection
Of Item With Waste
Management NMT-7



Visual Inspection
Of Item With Waste
Management NMT-7



Visual Inspection
Of Item With Waste
Management NMT-7




Drum Configuration
Targeted Materials





**Drum Storage Ready For Shipment Flow Chart** 



### Package Survey Instructions

Scope: This form will be used to collect data on LANL nuclear material packages. The data will be collected in a database and used to PREDICT AND PREVENT FUTURE PACKAGE FAILURES. Thus, it is important to collect as much accurate data as possible. Please return this form to your surpervisor

### Use this form when:

- Versiying puckage type and megnity
  Repackaging nuclear materials
- · Packaging materials for discard to WIFP
- . Opening an item for processing
- · In conjunction with MC&A liventery

Please use the photographs previded below as a guide to filling our the form:

### Photos & Definitions of Typical Package Conditions

### Punctured

Penetrations of any size, shape or form with the exception of allowable filtered penetration, or filler, which may leak material due to a peneuration or loose tape attacking the filter.







A food pack container shall be considered based if any portion of the hid other than the rim touches a straight edge placed across the rist or sidewall is visibly not straight.

**Bulging Condition** 




Corresion, other than shight surface rast, which appears to threater container integrity, such as visible pitting or flakes of rust.

Deformation of the double scam or side seam of food pack, cans, or in the pinch point, or stress lines.



A container shall be considered 'paneled", if the side wails are dented in a manner that appears to indicate negative pressure or depressurization of the container.





### **Package Survey Instructions**

**Scope:** This form will be used to collect data on LANL nuclear material packages. The data will be collected in a database and used to *PREDICT AND PREVENT FUTURE PACKAGE FAILURES*. Thus, it is important to collect as much accurate data as possible. Please return this form to your surpervisor.

### Use this form when:

- Verifying package type and integrity
- Repackaging nuclear materials
- · Packaging materials for discard to WIPP
- Opening an item for processing
- In conjunction with MC&A Inventory

Please use the photographs provided below as a guide to filling out the form:

### Photos & Definitions of Typical Package Conditions

### **Punctured**

Penetrations of any size, shape or form with the exception of allowable filtered penetration, or filters, which may leak material due to a penetration or loose tape attaching the filter.

### **Dented**

Deformation of the double seam or side seam of food pack, cans, or in the surface of the can with sharp crease, pinch point, or stress lines.



**Bulging Condition** 

A food pack container shall be considered bulged if any portion of the lid other than the rim touches a straight edge placed across the rim or sidewall is visibly not straight.




Corroded

Corrosion, other than slight surface rust, which appears to threaten container integrity, such as visible pitting or flakes of rust.



**Paneled Condition** 

A container shall be considered 'paneled', if the side walls are dented in a manner that appears to indicate negative pressure or depressurization of the container.



Screw Top Container

Intrinsically Sealed

Non-Standard

Slip Lid

Pressure Cooker

## ALL FIELDS ARE REQUIRED IF INFORMATION IS AVAILABLE

# **Package Survey Form**

TURN SHEET OVER FOR INSTRUCTIONS

Inspector Name Nancy	Gallegos	Z# 97073	Date Inspected	2/11/2004	
Reason for Inspection  Process  Repack  REP  Vault Inspection	Complete This Portion For PEP Only	aK Complete tem Meets Criteria tem Hazardous	Potential Contaminants  Date Retrieved From Vault	None 2/10/2004	
outer Container  uter Contamination?  uter Shielding  Outer Shielding Type  Lead Pewter  Outer Container Type  Welded Slip-Lid(SS) Slip-Lid(Tin) Paint Can Hagan Drum Food Pack  Outer Condition  Dented Cracked Corroded Discolored Bulging Punctured Liquid on Outside Residue on Outside Residue on Outside Other, Please Comment  Tape Placement  Around Lid Across Top Both  Tape Condition  N/A Like New Discolored Brittle Properly Adhering Not Properly Adhering Other, Please Comment  Outer Lid Placement  Set Properly Off Axis Other, Please Comment	JU07-9099 SNM 9 Net W	MT 52	Inner	Inner Container  Inner Container Contaminated?  Inner Shielding  Inner Shielding Type  Lead Pewter  Inside of Outer Container Rust Liquid Other, Please Comment  Condition of Bag and Tail	
	Beta/Gamma Before Shielding (mRem) @ contact  O  Beta/Gamma After Shielding (mRem) @ Contact  O  Item sent to NDA  Item Will Proceed To: WIPP Storage Process Floor  Waste Management ID  METCA81	Final Outermost Container Type:  Filtered Vault Container, Screw Top Filtered Vault Container, Clamp Top WIPP Drum ARIES Inner ARIES Outer 3013 Intrinsically Sealed Flashlight Pressure Cooker RTG Sealed NDA Source Conflat ZPPR Plates Food Pack Paint Can Slip Lid Other, Please Specify		Condition of Bag and Tail  Like New Brittle Darkened Adhering to Can Loose Tape Rips Condition of Seam Other, Please Comment  Inner Container Type  Slip-Lid(SS) Slip-Lid(Tin) Paint Can Food Pack Welded Glass Plastic  Tape Condition  No Tape Like New Discolored Brittle Properly Adhering Not Properly Adhering Other, Please Comment  Inner Container Condition  Like New Dented Cracked Corroded Discolored Bulging	

Additional Observations: